

Table of Contents

<p>1 Requirements and Acceptance for Cable and Wire Harness Assemblies 1-1</p> <p>1.1 Scope 1-1</p> <p>1.2 Purpose 1-1</p> <p>1.3 Approach To This Document 1-1</p> <p>1.4 Specialized Designs 1-1</p> <p>1.5 Terms and Definitions 1-1</p> <p>1.6 Classes of Products 1-1</p> <p>1.7 Document Hierarchy 1-2</p> <p>1.8 Tool and Equipment Control 1-2</p> <p>1.9 Observable Criteria 1-2</p> <p>1.10 Defects and Process Indicators 1-3</p> <p>1.11 Inspection Conditions 1-3</p> <p>1.11.1 Target 1-3</p> <p>1.11.2 Acceptable 1-3</p> <p>1.11.3 Process Indicator 1-3</p> <p>1.11.4 Defect 1-3</p> <p>1.11.5 Disposition 1-3</p> <p>1.11.6 Product Classification Implied Relationships 1-4</p> <p>1.11.7 Conditions Not Specified 1-4</p> <p>1.12 Electrical Clearance 1-4</p> <p>1.13 Measurement Units and Applications 1-4</p> <p>1.14 Verification of Dimensions 1-5</p> <p>1.15 Visual Inspection 1-5</p> <p>1.15.1 Lighting 1-5</p> <p>1.15.2 Magnification 1-5</p> <p>1.16 Electrostatic Discharge (ESD) Protection 1-5</p> <p>1.17 Workmanship/Handling 1-5</p> <p>1.18 Cleaning 1-5</p>	<p>2 Applicable Documents 2-1</p> <p>2.1 IPC 2-1</p> <p>2.2 Joint Industry Standards (ANSI J-STD) 2-1</p> <p>2.3 Department of Defense (Military) 2-2</p> <p>2.4 American National Standards Institute (ANSI) 2-2</p> <p>2.5 ESD Associations (ESDA) 2-2</p> <p>3 Preparation 3-1</p> <p>3.1 Strand Damage 3-2</p> <p>3.2 Conductor - Deformation 3-3</p> <p>3.3 Wire Separation (Birdcaging) 3-3</p> <p>3.4 Damaged Insulation 3-5</p> <p>4 Soldered Terminations 4-1</p> <p>4.1 Wire Preparation, Tinning 4-2</p> <p>4.2 Parts Preparation, Gold Removal 4-3</p> <p>4.3 Cleanliness 4-4</p> <p>4.3.1 Prior to Soldering 4-4</p> <p>4.3.2 Solder Connections 4-4</p> <p>4.3.3 Particulate Matter 4-4</p> <p>4.3.4 Flux Residue 4-5</p> <p>4.4 Insulation 4-6</p> <p>4.4.1 Clearance 4-6</p> <p>4.4.2 Damage from Soldering 4-7</p> <p>4.5 Flexible Sleeve Insulation 4-9</p> <p>4.6 Birdcaged Wire (Soldered) 4-11</p>
---	---

Table of Contents (cont.)

4.7 Connection Requirements	4-12	6.2 Discrete Wire Termination	6-9
4.7.1 Terminals	4-12	6.2.1 General	6-9
4.7.2 Turret Terminals	4-12	6.2.2 Position of Wire	6-10
4.7.3 Bifurcated Terminals	4-14	6.2.3 Overhang (Extension)	6-11
4.7.3.1 Side Route Attachments	4-14	6.2.4 Wire Holder	6-13
4.7.3.2 Bottom and Top Route Attachments	4-16	6.2.5 Damage in Connection Area	6-15
4.7.3.3 Staked Wires	4-17	6.2.6 End Connectors	6-16
4.7.4 Slotted Terminals	4-18	6.2.7 Wiremount Connectors	6-18
4.7.5 Pierced/Perforated/Punched Terminals	4-19	6.2.8 Subminiature D-Connector (Series Bus Connector)	6-19
4.7.6 Hook Terminals	4-20	6.2.9 Modular Connectors (RJ Type)	6-21
4.7.7 Cup Terminals	4-21	7 Ultrasonic Welding	7-1
4.7.8 Series Connected Terminals	4-22	7.1 Insulation Clearance	7-2
4.8 Solder Requirements	4-23	7.2 Weld Nugget	7-3
4.8.1 General	4-24	7.2.1 Geometry	7-3
4.8.2 Fillet	4-25	8 Splices	8-1
4.8.3 Turret Terminals	4-27	8.1 Soldered Splices	8-2
4.8.4 Bifurcated Terminals	4-28	8.1.1 Mesh	8-2
4.8.5 Slotted Terminals	4-29	8.1.2 Wrap	8-3
4.8.6 Pierced/Perforated Terminals	4-30	8.1.3 Hook	8-4
4.8.7 Hook Terminals	4-31	8.1.4 Lap	8-5
4.8.8 Cup Terminals	4-32	8.2 Splices - Crimped	8-6
5 Crimp Terminations	5-1	8.2.1 Barrel	8-6
5.1 Stamped and Formed Contacts	5-2	8.2.2 Double Sided	8-8
5.1.1 Insulation Support Crimp	5-3	8.3 Splices - Ultrasonic Welded	8-11
5.1.2 Insulation Inspection Window	5-6	9 Connectorization	9-1
5.1.3 Conductor Crimp	5-7	9.1 Hardware Mounting	9-2
5.1.4 Crimp Bellmouth	5-10	9.1.1 Jackscrews	9-2
5.1.5 Conductor Brush	5-11	9.2 Strain Relief	9-3
5.1.6 Carrier Cutoff Tab	5-14	9.2.1 Sleeving	9-3
5.2 Machined Crimp Contacts	5-15	9.3 Sleeving and Boots	9-4
5.2.1 Insulation Clearance	5-15	9.3.1 Position	9-4
5.2.2 Insulation Support (Insulation Support Style Contacts)	5-17	9.3.2 Bonding - Conductive Adhesive	9-5
5.2.3 Conductor Location	5-18	9.4 Connector Damage	9-7
5.2.4 Crimping	5-20	9.4.1 Criteria	9-7
5.2.5 Under Size Conductor - CMA Buildup Crimps	5-22	9.4.2 Limits - Hard Face - Mating Surface	9-8
6 Insulation Displacement Connection (IDC)	6-1	9.4.3 Limits - Soft Face - Mating Surface or Rear Seal Area	9-9
6.1 Mass Termination, Flat Cable	6-2	9.4.4 Contacts	9-10
6.1.1 End Cutting	6-2		
6.1.2 Notching	6-3		
6.1.3 Planar Ground Plane Removal	6-4		
6.1.4 Connector Position	6-5		
6.1.5 Connector Skew and Lateral Position	6-7		
6.1.6 Retention	6-8		

Table of Contents (cont.)

10 Molding/Potting	10-1	13.2 Center Conductor Termination	13-4
10.1 Molding	10-2	13.2.1 Crimp	13-4
10.1.1 Insulation Damage	10-2	13.2.2 Solder	13-6
10.1.2 Filling	10-3	13.3 Solder Ferrule Pins	13-8
10.1.3 Terminal Positioning	10-5	13.3.1 General	13-8
10.1.4 Fit to Wire or Cable	10-6	13.3.2 Insulation	13-10
10.1.5 Flashing	10-8	13.4 Coaxial Connector - Printed Wire Board Mount	13-11
10.1.6 Chill Marks (Knit Lines), Stress Lines or Cracks	10-9	13.5 Coaxial Connector - Center Conductor Length - Right Angle Connector	13-12
10.1.7 Compound Color	10-9	13.6 Terminal Cover - Soldering	13-14
10.2 Potting	10-10	13.7 Shield Termination	13-16
10.2.1 Filling	10-10	13.7.1 Clamped Ground Rings	13-16
10.2.2 Fit to Wire or Cable	10-11	13.7.2 Crimped Ferrule	13-17
10.2.3 Curing	10-12	13.8 Center Pin Position	13-19
11 Cable Assemblies and Wires	11-1	13.9 Semirigid Coax	13-20
11.1 Cable Assemblies	11-2	13.9.1 Bending and Deformation	13-20
11.1.1 Reference Surfaces	11-2	13.9.2 Surface Condition	13-23
11.1.1.1 Straight/Axial Connectors	11-2	13.9.3 Dielectric Cutoff	13-24
11.1.1.2 Right-Angle Connectors	11-2	13.9.4 Dielectric Cleanliness	13-27
11.1.2 Length Measurement	11-3	13.9.5 Solder	13-28
11.2 Wires (As an Assembly)	11-4	13.10 Swage-Type Connector	13-30
11.2.1 Electrical Terminal Reference Location	11-4	13.11 Soldering and Stripping of Biaxial or Twinaxial Wire - Low Temperature Insulation	13-31
11.2.2 Length Measurement	11-5	13.11.1 Jacket and Tip Installation	13-31
12 Marking/Labeling	12-1	13.11.2 Ring Installation	13-33
12.1 Content	12-2	14 Wire Bundle Securing	14-1
12.2 Legibility	12-2	14.1 Tie Wrap/Lacing Application	14-2
12.3 Permanency	12-4	14.1.1 Tightness	14-6
12.4 Location	12-4	14.1.2 Damage	14-7
12.5 Functionality	12-5	14.1.3 Spacing	14-8
12.6 Marker Sleeve	12-6	14.2 Breakouts	14-9
12.6.1 Wrap Around	12-6	14.2.1 Individual Wires	14-9
12.6.2 Tubular	12-8	14.2.2 Spacing	14-10
13 Coaxial and Twinaxial Cable Assemblies	13-1		
13.1 Stripping	13-2		

Table of Contents (cont.)

14.3 Wire Bundles	14-13	17 Installation	17-1
14.3.1 Wire Crossover	14-13	17.1 General	17-2
14.3.2 Coaxial Cable Routing	14-14	17.2 Hardware Installation	17-3
14.3.3 Unused Wire Termination	14-15	17.2.1 Sequence	17-4
14.3.4 Ties over Splices and Ferrules	14-16	17.2.2 Type and Missing	17-6
15 Shielding	15-1	17.2.3 Minimum Torque for Electrical Connections	17-7
15.1 Braided	15-2	17.2.4 Wires	17-8
15.1.1 Direct Applied	15-3	17.2.5 High Voltage Applications	17-11
15.1.2 Pre-Woven	15-4	17.3 Wire/Harness Installation	17-12
15.2 Shield Termination	15-5	17.3.1 Stress Relief	17-12
15.2.1 Pick Off	15-5	17.3.2 Wire Dress	17-13
15.2.2 No Pick Off	15-11	17.3.3 Service Loops	17-14
15.2.3 Low Temperature Insulated Wire - With Pick Off	15-13	18 Solderless Wrap	18-1
15.3 Shield Termination - Shrink and Crimp	15-15	18.1 Number of Turns	18-2
15.4 Shield Termination - Splicing	15-19	18.2 Turn Spacing	18-3
15.5 Tapes - Barrier and Conductive, Adhesive or Non-Adhesive	15-21	18.3 End Tails, Insulation Wrap	18-4
15.6 Conduit (Shielding)	12-22	18.4 Raised Turns Overlap	18-6
15.7 Conductive Coating	15-23	18.5 Connection Position	18-7
15.8 Shrink Tubing - Conductive Lined	15-24	18.6 Wire Dress	18-9
16 Cable/Wire Harness Protective Coverings	16-1	18.7 Wire Slack	18-10
16.1 Braid	16-2	18.8 Plating	18-11
16.1.1 Direct Applied	16-2	18.9 Damage	18-12
16.1.2 Pre-Woven	16-4	18.9.1 Insulation	18-12
16.2 Taping	16-5	18.9.2 Wires and Terminals	18-13
16.3 Sleeving	16-6	Appendix A	A-1
16.3.1 Shrink Tubing	16-6	Appendix B	B-1
16.4 Spiral Plastic Wrap (Spiral Wrap Sleeving)	16-7	Standard Improvement Form	
16.5 Conduit (Containment)	16-8		